


Dempster & Lehigh Intersection Improvements

- This important and heavily-utilized intersection was mentioned many times during engagement as an area of safety concerns
- Opportunities for improving safety include: traffic signal adjustments, crossing visibility improvements (e.g. advance warning signage), trail wayfinding signage, and intersection geometry improvements (pictured below)
- A rail and vehicle overpass is likely prohibitively complex and costly. A trail overpass may be more feasible and less expensive, but still likely more costly than the typical trail overpass due to the complexities of the site.

Intersection Geometry Improvements



Existing Conditions



Wayfinding Signage Examples

What do you think of the proposed improvements?